

Oil Field Environmental Incident Summary

Incident: 20141101073134 **Date/Time of Notice:** 11/01/2014 07:31

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PEDERSON 1-33H

Field Name: PARSHALL

Well File #: 16746

Date Incident: 10/31/2014 **Time Incident:** 07:01

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 90

Sec: 33

Qtr: NW NW

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2.5	Barrels	2.5	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

Potential Environmental Impacts:

Low

Action Taken or Planned:

Manway hatch was tightend stopping the release. A vac truck was called in to remove the free fluid and a cleanup crew will be brought in to remove the affected material if needed.

Wastes Disposal Location: Fluids were taken to SWD, solids will be taken to Clean Harbors at Sawyer ND.

Agencies Involved:

Updates

Date: 11/3/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.